

## **ABSEIL ACCESS LTD**

## **Reference Project**

## Inspection and Maintenance

Location: NZMP Hawera and other milk

processing plants

Date: ongoing since 1994

Client: Fonterra

Abseil Access provide rope access services to the milk processing industry.

NZMP in Hawera have 8 stainless steel driers which require full surface crack detection and weld repairs. All this work is complicated by strict hygiene requirements, confined spaces, short shut down periods and minimal rope anchorage points.

Some of the circular drier chambers are 15m in diameter. To achieve full coverage of the internal circumference Abseil Access Ltd have designed and built an aluminium telescopic modular truss boom which is suspended from a single mid point. Inspectors work in pairs and a systematic approach can be easily achieved.

Cyclones, ring driers, ducting and silos are also inspected. Repairs are welded using NZ 4703 certified welders.











ABSEIL ACCESS LTD

15 Bute Street
P.O. Box 10717, Wellington
Phone and Fax: 04 801 5336
www.abseilaccess.co.nz
info@abseilaccess.co.nz

DJ Matheson 0274 449 774 djmatheson@abseilaccess.co.nz

Martin Wilson 0274 495 408 mwilson@abseilaccess.co.nz









