

## Reference Project

## Inspection

The visual inspection of the iconic Majestic Centre globe sculpture anchors and associated components using rope access.

<b>Location</b>	Majestic Building, Wellington
<b>Date</b>	Annually: 2012 – Present
<b>Client</b>	FPM Solutions
<b>Consultant</b>	N/A

The “Majestic Earth” sculpture by renowned NZ artist Neil Dawson is suspended above the main atrium of the Majestic Centre, Wellington.

Following a failure of the support system in 2010 and the subsequent reinstallation (by Abseil Access), Abseil Access have been requested to conduct an annual Close Visual Inspection (CVI) of the sculpture and its attachment points.

#### The work included:

- Developing an access, rescue, and general public access control plan
- Photographic record of key anchoring components
- Generating detailed visual inspection reports for comparable results

Abseil Access completes this annual inspection after work hours for minimal public interference. We provide an accurate and detailed condition monitoring program of these anchors, cables and fittings.

